

3M™ Scotchkote™ Epoxy Metal Repair XG 509

Data Sheet and Application Guide

Product Description

3M Scotchkote Epoxy Metal Repair XG 509 has been specifically developed as a high performance repair system with extended working time for rebuilding and repairing equipment requiring good mechanical strength, making the product ideal for use in warm environments.

Product Features

- Good application characteristics with good build characteristics.
- Designed for application by trowel or spatula at thicknesses up to 12mm.
- Outstanding cold weld capabilities.
- Suitable for use to repair cracked castings and rebuilding worn shafts, bearing housings, flanges etc.
- Excellent adhesion to correctly prepared metal surfaces.

General Application Steps

1. Remove oil, grease and loosely adhering deposits.
2. Abrade by appropriate means to create a coarse profile.
3. Apply Scotchkote Epoxy Metal Repair XG 509 to the required thickness.
4. Allow to cure.
5. Visually inspect the system for defects.
6. Repair any defects.
7. Carry out machining as required.

Properties

Property	Value
Colour	Grey
Ratio	1:1 By volume 1.15:1 By weight
Drying & Cure times at 20°C (68°F)	
Useable life	60 mins
Initial Set	4 hours
Hard Dry for machining	12 hours
Full Mechanical Cure	5 days
Volume Solids	100%
Film Thickness	Upto 12mm.
Volume Capacity	392cc (23.94 cu ins) per kilo
Performance Data	
Flexural Strength	56Mpa (8000 psi) (ASTM D790)
Compressive Strength	70 Mpa (10000 psi) (ASTM D695)
Heat Distortion Temperature	60°C (140°F) (ASTM D648)
Tensile Shear Adhesion	17.24 Mpa (2500 psi) on grit blasted steel (ASTM D1002)
Corrosion Resistance	5000 hours (ASTM B117)
Shore D Hardness	85 (ASTM D2260)
Maximum Operating Temperature	120°C (248°F) - Dry 70°C (158°F) - Wet



Application Procedures for 3M™ Scotchkote™ Epoxy Metal Repair XG 509

Surface Preparation

Heavy contamination due to oil or grease must first be removed using 3M™ Scotchkote™ 020 Cleaner. All loose material, rust and surface contaminants, including existing coatings, must be removed and the surface roughened by using an angle grinder, needle gun or abrasive blasting.

When treating existing equipment which may have become salt impregnated due to service conditions, surfaces should first be wet blasted then dry blasted and tested for presence of salts. This process should be repeated until all salts are removed.

Where grinding or needle gunning is used, the surface should be cross-scored to improve adhesion. Care must be taken, when angle grinding, to avoid polishing rather than roughening metal surfaces. Where possible, abrasive blasting is the preferred surface preparation, especially in fluid flow repairs.

Surfaces should finally be carefully degreased using Scotchkote 020 Cleaner. Cloths should be frequently changed to avoid spreading contamination. On deeply pitted surfaces or porous castings, the cleaner should be worked into the surface by brush and washed off using excess cleaner.

Parts (for example, threads or bearing surfaces) which must remain in position during application but must not adhere to Scotchkote Epoxy Metal Repair XG 509 must be coated with 3M™ Scotchkote™ Release Agent 035 prior to application of the repair product.

Product Mixing

Scotchkote Epoxy Metal Repair XG509 is a two component solvent free material comprising Part A (Base) and Part B (Activator) components which must be mixed together prior to use.

Handling and Safety Precautions

Read all Health Hazard, Precautionary and First Aid, Material Safety Data Sheet, and/or product label prior to handling or use.

3M and Scotchkote are trademarks of 3M Company.

Important Notice

All statements, technical information, and recommendations related to 3M's products are based on information believed to be reliable, but the accuracy or completeness is not guaranteed. Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use. Any statements related to the product which are not contained in 3M's current publications, or any contrary statements contained on your purchase order shall have no force or effect unless expressly agreed upon, in writing, by an authorised officer of 3M.

Warranty; Limited Remedy; Limited Liability.

This product will be free from defects in material and manufacture for a period of 12 months from the time of purchase. **3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF QUALITY OR FITNESS FOR A PARTICULAR PURPOSE.** If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. **Except where prohibited by law, 3M will not be liable for any loss or damage arising from this 3M product, whether indirect, special, incidental or consequential (including, but not limited to, loss of profits, business and/or goodwill) regardless of the legal theory. For the sake of clarity, nothing in this statement will be deemed to exclude or restrict 3M's liability for death or personal injury arising from its own negligence.**

Measure equal volumes of Part A (Base) component and Part B (Activator) component onto a clean mixing board or other suitable surface. The two components should then be thoroughly mixed until completely streak free.

The mixed material should be used within 60 minutes of mixing at 20°C (68°F). This time will be reduced at higher temperatures and extended at lower temperatures.

Application Procedures

The mixed material should be pressed firmly onto the prepared area, working the material into any cracks and surface defects.

When Scotchkote Metal Repair XG 509 is being used to bond two surfaces together, both surfaces should be coated with the material. The two pieces should then be pressed firmly together and clamped in position until the product has set, any excess material squeezed out should be scraped away before the product begins to cure.

When 3M™ Scotchkote Reinforcement Tape 040 is being used to strengthen the repairs the tape should either be impregnated with Scotchkote Epoxy Metal Repair XG 509 or the tape should be laid over the Scotchkote Epoxy Metal Repair XG 509 surface and stippled into the material before it cures, then additional Scotchkote Epoxy Metal Repair XG 509 applied over the surface.

Packaging and Storage

Supplied in 3 kilo packs

Use within 5 years of date of manufacture. Store in original sealed containers at temperatures between 5°C and 32°C.

Ordering Information/Customer Service

For ordering, technical and product information or to request a copy of the Material Safety Data Sheet, call +44 (0)1609 780170 or fax +44 (0)1609 783762 (Sales) or 788718 (Technical).

For emergencies, please contact +44 (0)1344 858000.



Corrosion Protection Products 3M United Kingdom plc

23 Standard Way Industrial Estate
Northallerton
North Yorkshire DL6 2XA
United Kingdom
Phone: +44 (0)1609 780170
Fax: +44 (0)1609 780438
www.3M.co.uk/scotchkote

Corrosion Protection Products 3M United Kingdom plc

3M Centre
Cain Road, Bracknell
Berkshire RG12 8HT
Phone: 01344 858000
Fax: 01344 857970
www.3M.co.uk

Please recycle. Printed in UK.
© 3M 2010. All rights reserved.
XG509-0811